INVOICE

you again in the future.

ORD # 98-02-006 INVOICE # 971999

TERMS Net 30 Days

FEB 26 1998

02/21/98 12:58:11

ATTEN Accounts Receivable PHONE (317) 290-1471

INVOICE Milbank Manufacturing Company REMIT See Below TO 1400 E. Havens

P.O. Box 754

Kokomo, IN 46903-0754

ATTEN Ronda S. Yeakley

WORK ID Effluent Water Composite

P.O. # 206941 Thank you for your business. We look forward to working with

REPORT Milbank Manufacturing Company

TO 1400 E. Havens

P.O. Box 754

Kokomo, IN 46903-0754

ATTEN Ronda S. Yeakley

RECEIVED 02/02/98 CLIENT MILBANK MFG

REPORTED 02/05/98 PROJECT


ID CODE DESCRIPTION

REMARK

PRICE QTY DISCOUNT AMOUNT

ZN_IC Zinc, ICAPES







CERTIFICATE OF ANALYSIS

Milbank Manufacturing Company

1400 E. Havens P.O. Box 754

Kokomo, IN 46903-0754 Attn: Ronda S. Yeakley

Purchase Order: 206941

Invoice Number:

Order #: 98-02-006 Date: 02/05/98 07:42

Work ID: Effluent Water Composite

Date Received: 02/02/98 Date Completed: 02/04/98

Client Code: MILBANK MFG

SAMPLE IDENTIFICATION

Sample Sample

Number Description

O1 Effluent Composite

Sample

Sample

Number

Description

This report may not be reproduced except in full, without the written approval of the laboratory. All results relate only

to the items tested.

This report contains a total number of pages: 02

Certified By



Order # 98-02-006 02/05/98 07:42

TEST RESULTS BY SAMPLE

Page 2

Sample: 01AW Effluent Composite

Collected: 01/30/98 Category: WATER

Test Description Zinc, ICAPES

Result 1.380 <u>Limit</u> 0.010

<u>Units</u> <u>Analyzed</u> <u>By</u>

mg/L 02/04/98 JAR





ESC pratories

5933 West 71" Street * Indianapolis, IN 46278 Phone (317) 290-1471 * Fax (317) 290-1670

CHAIN OF CUSTODY RECORD

1	کو م
	100

Sampler(s) Signature:			Project Name:				Total Number of Containers	Filtered (Y or N) Preserv. Code Analyses			7		 	7	7	7	Comments	Preservation Codes: A = Acid B = Base C = Cool 4°
Stat.140	1-30-95	-	×	I	E. F. Thear		/	<u> </u>	Ĺ	Ĺ	Í				Í	Í		
	150-77	7-3_			674/vent													
														1				The state of the s
									1				-					
						-												
																(5)	2 5 u	
				2													and the second	
																	3	
		<u>.</u>											<u> </u>					
							ļ								ļ			
									-									·
														.~				
							-		l					ļ				
					Λ/a													
fut & ala >290 \$1/2/2			10:4															
Relinquished By:			Date / Time Received By:				Date / Time		suspected to be: Flammable Corrosive Toxic s received intact and properly preserved? Yes No									
Relinquished By: Date / Ti			Time	Received By:	L	Temp. BlankC												